

### PCI WEIGHT OF 10

Activity	Impact.amt	Impact.unit
AC - AC Overlay > 2"	100	Absolute
AC - Patching - Full Depth	25	%
AC - Patching - Partial Depth	25	%
AC - Pothole Filling	25	%
AC - Reconstruct - Full	100	Absolute
PCC - AC Overlay > 2"	100	Absolute
PCC - Patching - Full Depth	25	%

### CONDITION WEIGHT OF 8

NO IMPACT ACTIVITIES IDENTIFIED

### RIDE WEIGHT OF 3

Activity	Impact.amt	Impact.unit
AC - AC Overlay > 2"	90	Absolute
AC - Patching - Full Depth	50	%
AC - Patching - Partial Depth	50	%
AC - Pothole Filling	50	%
AC - Reconstruct - Full	90	Absolute
PCC - AC Overlay > 2"	90	Absolute
PCC - Patching - Full Depth	50	%

### CONDITION GROUPS

Condition Group	Minimum Index	Minimum Rating
Rural Arterial	81	Excellent
Rural Collector	61	Good
Rural Local	21	Fair
Urban Arterial	81	Excellent
Urban Collector	61	Good
Urban Local	41	Average